



## VIDEO CAMERA

FAMILY CODE: **31144**

The windshield-mounted video camera is an advanced driver assistance system (ADAS) and electronic device that assists the driver while driving.



NON-EMITTED CO<sub>2</sub>\*: *under investigation*



MATERIAL SAVINGS\*: **0,114 kg**

\*Source: Life-Cycle Assessment (LCA) Europe.  
Based on a European study Material savings and non-emitted CO<sub>2</sub> on average compared with the new equivalent MOPAR genuine part. Values are given for information only, corresponding to the main seller of the similar products and determined according to a methodology approved by an independent company (Sphera methodology).



## REMANUFACTURING STEPS

- Cleaning of the unit
- Reading of the list of faults to identify failures
- Preventive replacement of all worn and fragile components to ensure long-term durability
- Full operational test on a simulation bench
- Fitting on the vehicle, identical to the genuine part, including the calibration download process



## MAINTENANCE & REPAIR GUIDELINES

The video camera must be replaced or recalibrated:

- When the windshield is replaced
- When an ADAS is not working properly



## ADDITIONAL CHECKPOINTS

- Windshield
- Camera Calibration

EE SA NA

