



## POWER STEERING PUMP

FAMILY CODE: **30144**

The electropump assembly enables the power steering. It makes maneuvering easier for the driver by reducing the amount of effort required.



NON-EMITTED CO<sub>2</sub>\*: **20,2 kg**



MATERIAL SAVINGS\*: **4,73 kg**

\*Source: Life-Cycle Assessment (LCA) Europe.  
Based on a European study Material savings and non-emitted CO<sub>2</sub> on average compared with the new equivalent MOPAR genuine part. Values are given for information only, corresponding to the main seller of the similar products and determined according to a methodology approved by an independent company (Sphera methodology).



## REMANUFACTURING STEPS

- Full dismantling of components
- Component checks (dimensions and functions)
- Clean and recondition all parts to their original condition
- Replace damaged or worn parts with new components
- Test the part



## MAINTENANCE & REPAIR GUIDELINES

The electropump assembly must be replaced when:

- The power steering is not working, leading to difficulty with turning the steering wheel



## ADDITIONAL CHECKPOINTS

- Power steering fluid
- Steering rack
- Steering rods

EE SA NA

