



AUTORADIO

FAMILY CODE: 85072

An audio system is the central component of a sound reproduction system installed in a vehicle.





- Clean the unit and connectors
- Read the list of faults to identify failures
- Preventive replacement of all worn and fragile components
- Full operational test on a test bench
- Fitting on the vehicle, identical to the genuine part including the calibration download process if required




The autoradio system must be replaced when:

- The memory function can no longer be activated
- The audio system is silent
- A CD is stuck inside the player
- The sound level is not gradual
- The navigation no longer works



- The SIM card or navigation CD
- The speakers
- The aerial cable



*Source: Life-Cycle Assessment (LCA) Europe.

Based on a European study Material savings and non-emitted CO_2 on average compared with the new equivalent MOPAR genuine part. Values are given for information only, corresponding to the main seller of the similar products and determined according to a methodology approved by an independent company (Sphera methodology).