



DISPLAY

FAMILY CODE: **028 / 31844**

The display is normally integrated into the dashboard and allows the visualization of various information and the use of the different functions offered by the on-board computer.



NON-EMITTED CO₂*: *under investigation*



MATERIAL SAVINGS*: *under investigation*

*Source: Life-Cycle Assessment (LCA) Europe.
Based on a European study Material savings and non-emitted CO₂ on average compared with the new equivalent MOPAR genuine part. Values are given for information only, corresponding to the main seller of the similar products and determined according to a methodology approved by an independent company (Sphera methodology).



REMANUFACTURING STEPS

- Review the list of faults to identify failures
- Preventive replacement of all worn components
- Each part is tested to ensure the same performance as the genuine part
- Fitting on the identical to the genuine part



MAINTENANCE & REPAIR GUIDELINES

- The display must be replaced when:
- Nothing appears on the screen or has some pixel dysfunction
- Some commands do not work anymore
- Sleep mode does not work



ADDITIONAL CHECKPOINTS

- Radio, air conditioning, navigation.... Functionalities.

EE SA NA

